


1
2
3
4
5



CAUTION
When taking a broken fuse (F603) of
discharge across C604 to avoid shock
hazard.

NOTE: BA Board

When replacing L313A, L319, L320, mount so that they closely touch the board.